

Tranax Error Codes

Code	Description	Resolution
<input type="checkbox"/> 00000	Normal Status	Normal Status
<input type="checkbox"/> 20001	Unable to detect a cassette	Remove and replace cassette - Check the micro-switch located on the inside left wall of the dispenser. Adjust the micro-switch if needed, also check the white plastic clips that hold the cassette in place. If they are broken the cassette will not stay in the dispenser.
<input type="checkbox"/> 20002	Low Cash	Low cash warning sensor on dispenser is open. When "Low Cash Warning" is enabled in the Transaction Setup menu, this sensor will open when the cassette reaches (+/-) 75 bills. If this machine is typically stocked with a low amount of bills, we recommend disabling this function.
<input type="checkbox"/> 20003	Reject Bin is Full	Empty reject bin - if bin is empty, do a Cassette Total (from the settlement menu) - If that doesn't help then check that AP, BIOS and CDU ROM versions are compatible.
<input type="checkbox"/> 20004	Vault Door is Open	This error occurs when the circuit between the mainboard and the door switch is open. Check vault door switch. This white plunger switch is located in the upper left corner of the vault, or on along the front edge of the cash dispenser tray. Also check that black and white, 2 wire connector is properly connected at rear of main board. Move the vault switch forward to aid door clearance problems. Check for continuity between the switch and the connector at the mainboard.
<input type="checkbox"/> 20005	CDU Type Mismatch	CDU ROM does not match AP software. The dispenser and mainboard are programmed with a country code (USA or Canada). The two codes must match. If they do not the 20005 error will occur in which case the CDU will need to be reprogrammed to match the AP on the mainboard. Also, if the wrong parameters are entered when the CDU is programmed, this error can occur.
<input type="checkbox"/> 20010	Receipt Paper Jam	Remove jammed paper - Release receipt paper drawer by pressing the tab with the green sticker located at the front of the printer. In most cases you may have to remove the printer to locate difficult jams. NOTE: Do NOT use metal objects to clear jams, use a business card or stiff paper. Make sure you only are using 21# paper. Paper of a lesser thickness is more prone to jamming.
<input type="checkbox"/> 20012	Receipt printer feed lever open	Close the feed tray on the printer. If the paper tray is already closed, try opening and closing the tray, try the printer reset switch. Otherwise the printer may require service.

<input type="checkbox"/>	20013	Receipt paper is empty	Replenish the paper roll, if there is already paper in the printer look for jams or obstructions. Try the printer reset switch. If it still has the error the printer may require service.
<input type="checkbox"/>	20014	Thermal printer is overheated	If this error occurs during the printing of a long journal, then allow the printer to cool and try again. You may also want to try the reset button on the printer to clear this error. If this error persists, the printer will require service.
<input type="checkbox"/>	20215	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS2 sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseal all belts. Loose belts can slip off rollers and block sensors.
<input type="checkbox"/>	21315	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS13 sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseal all belts. Loose belts can slip off rollers and block sensors.
<input type="checkbox"/>	21A15	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS1A sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseal all belts. Loose belts can slip off rollers and block sensors.
<input type="checkbox"/>	21B15	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS1B sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseal all belts. Loose belts can slip off rollers and block sensors.
<input type="checkbox"/>	24A15	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS4A sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseal all belts. Loose belts can slip off rollers and block sensors.
<input type="checkbox"/>	24B15	CDU detects bills prior to dispensing	This means that while the ATM was initializing it detected a blocked sensor in the cash dispenser (CS4B sensor). Remove any jammed bills from the dispenser, if no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Check and reseal all belts. Loose belts can slip off rollers and block sensors.
<input type="checkbox"/>	90001	Error during card swipe	This error occurs when customer attempts to swipe their card and are unsuccessful. It may indicate that the card reader needs to be cleaned. repositioned or simply that the customer

didn't swipe their card properly. If persistent, clean and test the card reader in diagnostics. NOTE: it is very common to see this error in the error summary and does not usually indicate a bad or defective part.

<input type="checkbox"/>	A0008	Receipt paper cutter error	Remove any jammed paper. You may need to remove the printer to clear jams. NOTE: Do not use metal objects to clear the jam. Use a business card or stiff paper to clear jams. Otherwise try the reset button or have the printer serviced.
<input type="checkbox"/>	A0803	Receipt Paper Jam	Remove jammed paper - Release receipt paper drawer by pressing the tab with the green sticker located at the front of the printer. You may need to remove the printer from the ATM to access the jam. NOTE: Do not use metal objects to clear jams, use a business card or stiff paper to poke around.
<input type="checkbox"/>	A0808	Receipt paper cutter error	Remove any jammed paper. You may need to remove the printer to clear jams. NOTE: Do not use metal objects to clear the jam. Use a business card or stiff paper to clear jams. Otherwise try the reset button or have the printer serviced.
<input type="checkbox"/>	ADN04	Printer connection error	Check cables between Printer and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner to clean the terminals. Try the reset button on the printer. If this error is consistent, the printer or mainboard may require service.
<input type="checkbox"/>	ADN0F	Printer connection error	Check cables between Printer and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner to clean the terminals. Try the reset button on the printer. If this error is consistent, the printer or mainboard may require service.
<input type="checkbox"/>	ADNxx	Printer connection error	Check cables between Printer and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner to clean the terminals. Try the reset button on the printer. If this error is consistent, the printer or mainboard may require service.
<input type="checkbox"/>	Axxx2	Thermal printer is overheated - during operation	If this error occurs during the printing of a long journal, then allow the printer to cool and try again. You may also want to try the reset button on the printer to clear this error. If this error persists, the printer will require service.
<input type="checkbox"/>	Axxx3	Receipt Paper Jam	Remove jammed paper - Release receipt paper drawer by pressing the tab with the green sticker located at the front of the printer. You may need to remove the printer from the ATM to access the jam. NOTE: Do NOT use metal objects to clear jams, use a business card or stiff paper to poke around.
<input type="checkbox"/>	Axxx4	Receipt paper is empty	Replenish the paper roll. If roll is ok, then try the reset button on the printer. Otherwise the printer needs service.

<input type="checkbox"/>	Axxx5	Receipt paper is jamming during loading	Remove any jammed paper and then reload. You may need to remove the printer to clear jams. NOTE: Do not use metal objects to clear the jam. Use a business card or stiff paper to clear jams. Otherwise try the reset button or have the printer serviced.
<input type="checkbox"/>	C0011	CDU sensor is tripped	This indicates that during a dispense, the sensor located at the front of the CDU shows a blockage (CS13 or CS2). The primary reason for this is a bill which bounces back from the cash tray (sometimes from a customers fingers). Check the front of the CDU and the cash tray for blockage. Reinitialize the ATM to put back in service. In the case of a dispute from the error, use CDU data in the journal to verify how many notes were actually dispensed.
<input type="checkbox"/>	C0014	CDU sensor is tripped	Similar to the C0011 error, this would indicate a bill jam close to the exit of the CDU or near the reject bin. Check for jammed notes or blocked sensors.
<input type="checkbox"/>	C001x	CDU sensor is tripped	Most typically a C0011 error, this would indicate a bill jam at the exit sensor of the Cash Dispenser. Usually caused by a customer putting fingers in the cash drawer during dispense. Other than upgrading the cash tray or using a sign to warn customers, you can loosen the screws that hold the dispenser and slide it back.
<input type="checkbox"/>	C0028	CDU sensor is tripped	Check dispenser for jammed bills and restart the machine. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
<input type="checkbox"/>	C002x	CDU sensor is tripped	Check dispenser for jammed bills and restart the machine. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
<input type="checkbox"/>	C0030	CDU motor failure	Motor speed (measured at the encoder wheel) was not within spec. Verify that CS8 or encoder wheel sensor is in place and wire connection is good. Can indicate a bad motor or encoder sensor.
<input type="checkbox"/>	C0031	CDU Gate solenoid error	The CDU did not respond to its solenoid function check. Check the wiring connections to the solenoid(s). Check wiring connections to the CDU main board.
<input type="checkbox"/>	C0032	Outlet solenoid error	Check and verify all connections to the dispenser circuit board. Check wiring to the solenoid(s).
<input type="checkbox"/>	C0033	CDU Encoder error	Usually caused by loss of battery power to the CDU mainboard. The only way to recover from this error is to reprogram the CDU data. This may require special software and cannot be

done over the phone line.

<input type="checkbox"/>	C0034	Double Note detect module failure	Double detect module reporting error, check wiring to the module.
<input type="checkbox"/>	C0035	Double Note detect module failure (2)	Double detect module reporting error, check wiring to the module.
<input type="checkbox"/>	C0036	Detected notes in path before initializing	One or more sensors in the dispenser detected a blockage prior to initializing. Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service.
<input type="checkbox"/>	C0037	Sensor(NS7) for detecting Double is covered during dispensing note	
<input type="checkbox"/>	C0039	Gate sensor open during initializing	Check the sensor that is activated when you close the reject bin door (2k/4k dispensers only). If the sensor is not being pressed then the error will occur. Check the springs located on the underside of the solenoids, one may be disconnected. Otherwise the CDU will require repair / replacement.
<input type="checkbox"/>	C003B	Notes detected during installation	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service.
<input type="checkbox"/>	C0040	Cassette removed during dispense	Reset the cassette, check position of microswitch on right rear wall of cassette bay in the dispenser. Check the condition of the white plastic cassette retaining clips in the dispenser.
<input type="checkbox"/>	C0041	Tried to dispense notes more than 5 times	Check the condition of the cash in the cassette. Verify that the cash is of good quality. The CDU belts or the Cassette rollers may need to be cleaned (rubbing alcohol). Check that the denomination in Transaction setup matches the actual denomination loaded.
<input type="checkbox"/>	C0042	Note jam	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
<input type="checkbox"/>	C0043	More than 10 notes rejected during one transaction	Verify the quality of the cash. Straighten and shuffle cash in the cassette. Check the reject analysis to determine the cause of reject (reports menu). If the cash is of known good quality then try cleaning the cassette and dispenser. Otherwise service to cassette or dispenser may be required.

<input type="checkbox"/>	C0044	More than 5 notes rejected consecutively	Verify the quality of the cash. Straighten and shuffle cash in the cassette. Check the reject analysis to determine the cause of reject (reports menu). If the cash is of known good quality then try cleaning the cassette and dispenser. Otherwise service to cassette or dispenser may be required.
<input type="checkbox"/>	C0046	CDU Hardware Failure	Error reported during CDU initialization. Check cabling and potential blockages and power cycle ATM.
<input type="checkbox"/>	C0047	Feed error	This error occurs when the dispenser attempts to pull a bill from the cassette and is unsuccessful before the dispenser times out. Depending on the model of dispenser there are different causes and possible solutions. It can be as simple as the cassette being empty, rollers need cleaning to a firmware upgrade to the CDU.
<input type="checkbox"/>	C0048	Incorrect bill count	Verify cash count in the Settlement menu.
<input type="checkbox"/>	C004A	Jammed notes	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
<input type="checkbox"/>	C004B	Long note detected 3 times consecutively	Verify the quality of the cash. Straighten and shuffle cash in the cassette. Try cleaning the cassette and dispenser. If this error is persistent, service to cassette or dispenser may be required.
<input type="checkbox"/>	C004C	Miscount of notes between sensors	Verify operation of exit gate. Check the number of dispensed notes. Clean the dispenser and test using diagnostics. Dispenser may require service.
<input type="checkbox"/>	C004D	Cash cassette not properly set	Reset the cassette, check position of microswitch on right rear wall of cassette bay in the dispenser. Check the condition of the white plastic cassette retaining clips in the dispenser. MB1000 check condition of the clutch alignment screw.
<input type="checkbox"/>	C004E	Miscount of notes between sensors	Test CDU using diagnostics, use journal to verify amount of dispensed notes versus requested notes. Clean dispenser and cassette. If error is persistent the dispenser may require service.
<input type="checkbox"/>	C004F	Miscount of notes between sensors	Test CDU using diagnostics, use journal to verify amount of dispensed notes versus requested notes. Clean dispenser and cassette. If error is persistent the dispenser may require service.
<input type="checkbox"/>	C0050	Power failure during dispense	Remove any notes from path. Before reinitializing the ATM, first the verify amount of dispensed notes in the cassette against the journal.
<input type="checkbox"/>	C0051	Over 150 notes requested	Possibly due to too many rejects, may require repair or

cleaning if consistent. Check the Reject Analysis, this may help determine the cause. Cash quality, condition of the rollers in the cassette can effect this condition.

<input type="checkbox"/>	C0052	Detected notes in path after dispense	Remove any notes from path, verify amount of dispensed notes. Clean dispenser. Verify the amount of bills against the journal.
<input type="checkbox"/>	C0053	CDU double detect module failure.	Double detect module may require adjustment. Check wiring and CDU mainboard connections.
<input type="checkbox"/>	C0055	Detected long notes at outlet sensor	(See definition of C0011 error) this is typically a bounce back of a bill during dispense causing the exit sensor to remain blocked for a longer time than is expected.
<input type="checkbox"/>	C0056	Exit gate sensor failure	Check condition of exit gate, and the exit gate sensor.
<input type="checkbox"/>	C0057	Cassette information is not properly set	CDU programming is not accurate or complete.
<input type="checkbox"/>	C0059	Cash cassette 2 removed prior to dispense.	Set the cash cassette. Inspect the cassette detection microswitch. Reposition the microswitch if necessary.
<input type="checkbox"/>	C005A	Cash cassette 1 removed prior to dispense	Set the cash cassette. Inspect the cassette detection microswitch. Reposition the microswitch if necessary.
<input type="checkbox"/>	C005B	Cash cassette 2 misfeed	Check cassette for jams, check condition of bills in cassette.
<input type="checkbox"/>	C005D	Double detect constantly	Inspect double detect module and adjust as necessary. Check and clean the cassette and rollers, verify the quality of cash.
<input type="checkbox"/>	C005E	Dispense command size check error	Re-initialize machine, verify connections to mainboard. Check for unplugged sensors.
<input type="checkbox"/>	C005F	Dispense command error	Re-initialize machine, verify connections, check for unplugged sensors.
<input type="checkbox"/>	C006x	Sensor failure	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service
<input type="checkbox"/>	C007x	Sensor failure	Check for notes in the Cash Dispenser. If no bills are present try using compressed air to clean the dispenser (a sensor may be blocked by dust). Otherwise the dispenser may require service

<input type="checkbox"/>	C0082	Shutter failure	Check all wiring connections to CDU mainboard. Reinitialize CDU
<input type="checkbox"/>	C0083	Stacker sensor failure	Check all wiring connections to CDU mainboard. Reinitialize CDU
<input type="checkbox"/>	C0084	Shutter close error	Check all wiring connections to CDU mainboard. Reinitialize CDU.
<input type="checkbox"/>	C009F	3Cassette misfeed error	Check if notes available in cassette
<input type="checkbox"/>	C00AB	Notes detected before initializing	Clear notes from dispenser. Possibly dust or foreign object blocking sensor.
<input type="checkbox"/>	C00C7	CS12 Sensor blocked	MB2100T - The CS12 sensor, which is located at the upper part of the cash tray was blocked while the machine was either dispensing or initializing. Clear the cash tray of any bills or foreign objects. If the error persists, the vault assembly may need to be removed to inspect / access the cash tray sensors.
<input type="checkbox"/>	C00C8	CS14 Sensor blocked	MB2100T - The CS14 sensor, which is located close to front of the cash tray, was blocked while the machine was either dispensing or initializing. Clear the cash tray of any bills or foreign objects. If the error persists, the vault assembly may need to be removed to inspect / access the cash tray sensors.
<input type="checkbox"/>	C00C9	CS12 & CS14 Sensors blocked	MB2100T - Both the CS12 and CS14 sensors were blocked while the machine was either dispensing or initializing. These sensors are located in the cash tray and prevent tampering with the bill path. Clear the cash tray of any bills or foreign objects. If the error persists, the vault assembly may need to be removed to inspect / access the cash tray sensors.
<input type="checkbox"/>	C00D0	Sensor block while dispensing	MB2100T - A blockage was detected between the CS13 (CDU exit gate) and CS12 cash tray sensors. There may be a note stuck in the upper part of the cash tray ramp. Try clearing the cash tray of notes or foreign objects. Open the vault and slide the dispenser back to access the exit gate area. Both sensors must be blocked for this error to occur.
<input type="checkbox"/>	C00D1	Sensor blocked while dispensing	MB2100T - A blockage was detected between the CS12 (upper cash tray sensor) and CS14 (lower cash tray sensor). There may be a note stuck in the cash tray ramp. Try clearing the cash tray of notes or foreign objects. Open the vault and slide the dispenser back to access the exit gate area. Both sensors must be blocked for this error to occur.
<input type="checkbox"/>	C00E0	NS2A, NS2B dark	Nanocash only - verify connections to sensors. Check wiring to mainboard.

<input type="checkbox"/>	C00E1	NS4 dark	Verify connections to NS4 sensor. Check all wiring to mainboard.
<input type="checkbox"/>	C00FF	Sensor blocked	N/A
<input type="checkbox"/>	CANCE	User canceled transaction at surcharge	This is not an error, but rather a statistic to notify how many users respond "no" to the surcharge notification.
<input type="checkbox"/>	CDN05	CDU connection failure	Check cables between CDU and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner on terminals. This error is of concern only if it is repeated. Outside interference may cause it (neon signs, lights).
<input type="checkbox"/>	CDN0F	CDU connection failure	Check cables between CDU and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner on terminals. This error is of concern only if it is repeated. Outside interference may cause it (neon signs, lights).
<input type="checkbox"/>	CDNxx	CDU connection failure	Check cables between CDU and Mainboard, remove cables (even though they may be attached) and re-connect. Use an electrical parts contact cleaner on terminals. This error is of concern only if it is repeated. Outside interference may cause it (neon signs, lights).
<input type="checkbox"/>	D0001	Modem initialization error	Check modem in diagnostics or modem test. If persistent, it could be a defective modem. Note: If the modem is defective, this error will most likely occur frequently. One or two instances of this error does not usually indicate a defective part.
<input type="checkbox"/>	D0002	Reversal transaction failed.	The ATM attempted to do a reversal and could not. Check transaction with the processor. Verify CDU functionality with diagnostics. Verify phone connection. Look in error summary for D1800, D2000.
<input type="checkbox"/>	D0005	Undefined network processing error	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0011	Format error in the message.	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0012	Invalid Transaction	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors. or you cannot complete a test transaction because of

this error.

<input type="checkbox"/>	D0013	Invalid Amount	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0014	Invalid Card Number	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0019	Reenter the entire transaction	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0020	Surcharge screen should have been displayed	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0024	Exceeds issuer withdrawal limit	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0031	Issuer financial institution is not supported by a processor	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0039	No credit account	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0041	No credit account found for the CCN	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0043	Stolen Card	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of

these errors, or you cannot complete a test transaction because of this error.

<input type="checkbox"/>	D0050	Transaction is not approved	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0051	Insufficient funds	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0052	No checking account	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0053	No savings account	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0054	Expired Card	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0055	Invalid PIN	Code reported from host processor - Verify all programming. In the case of a new installation, if master keys are not bound properly, Terminal ID is not active or if programming is not correct for the host this can occur. If all programming appears correct, contact the processor and have them trace the Terminal ID.
<input type="checkbox"/>	D0056	No card record found	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0057	Transaction not permitted - card	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0058	Transaction not permitted	Code reported by host processor. Specific meaning or definition

- Terminal

can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.

<input type="checkbox"/>	D0059	Customer should contact his or her financial institution	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
--------------------------	--------------	---	--

<input type="checkbox"/>	D0060	Allowable withdrawal limit is exceeded	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
--------------------------	--------------	---	---

<input type="checkbox"/>	D0061	Exceeded withdrawal limit	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
--------------------------	--------------	----------------------------------	---

<input type="checkbox"/>	D0065	Exceeds withdrawal frequency limit	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
--------------------------	--------------	---	---

<input type="checkbox"/>	D0067	Capture card at the terminal (requires card be picked up at ATM only).	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
--------------------------	--------------	---	--

<input type="checkbox"/>	D0075	Number of PIN tries exceeded	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
--------------------------	--------------	-------------------------------------	---

<input type="checkbox"/>	D0078	No Account	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
--------------------------	--------------	-------------------	---

<input type="checkbox"/>	D0080	Invalid Date	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
--------------------------	--------------	---------------------	---

<input type="checkbox"/>	D0081	Time out: response not received in time allowed (SHAZAM switch-in-front (SIF) terminals).	Code reported by host processor (Shazam). Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0082	Cashback limit exceeded.	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0083	Cannot verify PIN	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0084	Processor not available; acquirer processor unable to send message	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0086	Cannot verify PIN	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0090	Cutoff complete for terminal; cannot process prior days business	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0091	Bank unavailable	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0092	System unavailable	Code reported by host processor. Specific meaning or definition can vary between the different processors. Contact your ISO or processor if you encounter an excessive amount of these errors, or you cannot complete a test transaction because of this error.
<input type="checkbox"/>	D0093	Transaction serial number mismatch	Verify all programming, contact host processor
<input type="checkbox"/>	D0094	Record format mismatch	Verify all programming, contact host processor

<input type="checkbox"/>	D0095	Routing ID mismatch	Verify Routing ID number - contact host processor
<input type="checkbox"/>	D0096	Terminal ID mismatch	Verify Terminal ID number - contact host processor
<input type="checkbox"/>	D0097	Response type mismatch (reversal)	Verify all programming, contact host processor
<input type="checkbox"/>	D0098	Response type mismatch (day-close)	Verify all programming, contact host processor
<input type="checkbox"/>	D0099	Response type mismatch (Configuration)	Verify all programming, contact host processor
<input type="checkbox"/>	D009A	Response type mismatch (Withdrawal, Balance, Transfer)	Verify all programming, contact host processor
<input type="checkbox"/>	D009B	STX omitted	Verify all programming, contact host processor
<input type="checkbox"/>	D009C	ETX omitted	Verify all programming, contact host processor
<input type="checkbox"/>	D009D	FS omitted (after response code)	Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D009E	FS omitted (after retrieval reference number)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D009F	FS omitted (after system trace audit number)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D00A0	FS omitted (after account balance)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D00A1	FS omitted (after available balance)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D00A2	FS omitted (after available balance)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D00A3	FS omitted (after authorization response text)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor

<input type="checkbox"/>	D00A4	ETX is in wrong place	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D00A5	FS omitted (after total cash dispense amount in day close)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D00A6	FS omitted (after total non cash dispense amount in day close)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D00A7	FS omitted (after surcharge amount in day close message)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D00A8	FS omitted (after surcharge amount in configuration message)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Check that Dual Master Key is disabled (non Coredata). Contact host processor
<input type="checkbox"/>	D00A9	ETX omitted (from configuration message)	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D0300	Modem is not responding	Use diagnostic or modem test to test modem. If error is persistent, modem may be defective.
<input type="checkbox"/>	D1000	No Connection	Use diagnostic or modem test to test modem. If error is persistent, modem may be defective.
<input type="checkbox"/>	D1100	ENQ not received from host	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D1200	Transmission error	Use diagnostic or modem test to test modem. If error is persistent, modem may be defective
<input type="checkbox"/>	D1300	NAK sent 3 times to host	Verify host phone number - See D170x. If persistent, it could be a defective modem.
<input type="checkbox"/>	D1500	Modem connection time out - host not responding	Verify host phone number - verify modem speed - See D170x. If consistent, it can be a defective modem
<input type="checkbox"/>	D1702	Modem connection error	Phone line connected to ATM will not support data communication. In line filter may help this. Excessive EMI emissions from outside source (neon sign, freezer) are likely causes. This can also be a problem with programming, check all programming (especially Dual Master Key setting and Host Processor Mode).

<input type="checkbox"/>	D1704	Modem connection error	Phone line connected to ATM will not support data communication. In line filter may help this. Excessive EMI emissions from outside source (neon sign, freezer) are likely causes. This can also be a problem with programming, check all programming (especially Dual Master Key setting and Host Processor Mode).
<input type="checkbox"/>	D1706	Modem connection error	Phone line connected to ATM will not support data communication. In line filter may help this. Excessive EMI emissions from outside source (neon sign, freezer) are likely causes. This can also be a problem with programming, check all programming (especially Dual Master Key setting and Host Processor Mode).
<input type="checkbox"/>	D170x	Modem cannot support connection - excessive line noise (usually D1704/06)	Phone line connected to ATM will not support Data-communication. In line filter may fix this. Excessive EMI emissions from outside source (neon sign, freezer). This can also be a problem with programming, check all programming (especially Dual Master Key setting and Host Processor Mode).
<input type="checkbox"/>	D1800	No dial tone	Verify that incoming phone line is plugged into "Line" rather than "Phone" on mainboard. Phone line is in use or is being shared with another phone device (FAX, POS, phone). NOTE: This error occurs only if there is no dial tone at the mainboard.
<input type="checkbox"/>	D1900	No answer	Verify host phone number - See D170x, there is no answer from the host modem.
<input type="checkbox"/>	D2000	Phone line Busy	Verify host phone number - call line with handset and check for busy signal - See D170x. ATM modem is receiving a busy signal when it dials out.
<input type="checkbox"/>	D2100	Modem initialization error	Check modem in diagnostics or modem test. If persistent, it could be a defective modem. Note: If the modem is defective, this error will most likely occur frequently. One or two instances of this error does not usually indicate a defective part.
<input type="checkbox"/>	D2200	EOT not received from host	Verify all programming. Verify that version of Mini-Bank Software matches host processor. Contact host processor
<input type="checkbox"/>	D2500	Cannot connect to the host	Check the connection
	D3200	Host Numbers Timeout	Check the connection
<input type="checkbox"/>	D3204	Invalid Host phone number	Verify the Host phone number is programmed correctly. Do not use spaces or dashes in the phone number string.
<input type="checkbox"/>	E000x	RMS port failure, response time out, modem failure, no dial tone	Verify RMS settings (Host Setup) - See D170x

<input type="checkbox"/>	F0001	Current Number of Bills is 0	Load notes into the cash cassette - use Add Cassette function in Settlement
<input type="checkbox"/>	F0002	No Surcharge Owner set	Set Surcharge owner - (Customer Setup)
<input type="checkbox"/>	F0003	No Surcharge Amount	Set Surcharge amount - (Customer Setup)
<input type="checkbox"/>	F0004	No refresh timer set when advertisement is enabled	Set refresh timer - (Customer Setup)
<input type="checkbox"/>	F0005	No Advertisement text when advertisement is enabled	Set Advertisement text - (Customer Setup)
<input type="checkbox"/>	F0006	Dispense limit set error (must be less than 25 notes)	Set Dispense limit - (Transaction Setup)
<input type="checkbox"/>	F0007	Denomination Set error	Valid Denominations are \$10, \$20, \$50, \$100 - (Transaction Setup)
<input type="checkbox"/>	F0008	Fast Cash Set error (cannot exceed dispense limit)	Check fast cash settings (Transaction Setup)
<input type="checkbox"/>	F0009	Master Key index is invalid	Check Master Key index - verify checksum (Host Setup)
<input type="checkbox"/>	F000A	Master Key is empty	Check Master Key checksum - reinject key (Host Setup)
<input type="checkbox"/>	F000B	Host Telephone Number is not set	Set Host Telephone Number - (Host Setup)
<input type="checkbox"/>	F000C	Error Retry timer is not set	Set Error retry timer (Host Setup)
<input type="checkbox"/>	F000D	RMS Password is not set when RMS is enabled	Set RMS Password - (Host Setup)
<input type="checkbox"/>	F000E	RMS phone number is not set when RMS send is enabled	Set RMS Phone number - (Host Setup)

<input type="checkbox"/>	F000F	Terminal ID is not set	Set Terminal ID number - (Host Setup)
<input type="checkbox"/>	F0010	Routing ID is not set	Set Routing ID number - (Host Setup)
<input type="checkbox"/>	F0011	Master Key Serial number is not set	Set Master Key serial number - (Host Setup)
<input type="checkbox"/>	F0013	NVRAM Failure	Fatal error, defective memory chip. Replace Mainboard
<input type="checkbox"/>	F0014	NVRAM Failure	Fatal error, defective memory chip. Replace Mainboard
<input type="checkbox"/>	P0001	Deposit Error	Deposit Error
<input type="checkbox"/>	P0002	Deposit Timeout	Deposit Timeout
<input type="checkbox"/>	P0003	Invalid Deposit	Invalid Deposit
<input type="checkbox"/>	P0004	Deposit Cancelled	Deposit Cancelled
<input type="checkbox"/>	W0001	WebRMS failed to dial into the ATM	This does not mean that the ATM is down; it's a warning message that WebRMS could not dial into the ATM after three attempts during its daily scheduled dial-in period. Make sure the ATM is turned on, the phone line fits securely on both ends, and not shared with a voice phone nor experiences static.
<input type="checkbox"/>	W0002	WebRMS low cash warning	This is a courtesy alert warning, along with an email message, that you requested to receive when the total bill count is under a certain amount. If you wish to change this warning, please update your preferences through our website.
<input type="checkbox"/>	W0003	WebRMS could not retrieve the local ATM time	Although webRMS successfully retrieved the journal information, it could not find the ATM's local time. (This is equivalent to the "-1/-1/-001" error when using Windows RMS). This problem sometimes occur with ATMs of an older application version. Make sure you are running the latest application version.
<input type="checkbox"/>	W0004	The ATM time, as set in the Operator Function Menu, is incorrect	WebRMS has detected that the ATM probably has incorrect date and time settings. You will need to physically go to the ATM location and manually reset the correct date with the Master Password.
<input type="checkbox"/>	W0005	WebRMS coincidentally detected that the ATM was in Operator mode at the time the ATM was dialed into.	This is not an error in particular, but a simple warning that someone was locally on-site at the ATM, and used its Operator Function menu.



W0006

WebRMS has failed to dial into the ATM consecutively for more than 3 days.

Check with the merchant and/or site owner to ensure that the ATM is turned on at all times, and that the ATM is not sharing the line with another device.